

Ref.No. 46/MAR/2022

Date: 25.03.2022

To
The Principal
St.Paul's International School
NH- 60, Barshal, Rampurhat
Birbhum, West Bengal


Subject- Regarding Stability of Educational Institute building named "St. Paul's International School" Located at NH 60, Harloka, Barshal Ramurhat. Distt- Birbhum


Respected Sir,

In connection with the above subject. I would to inform you that the above mentioned building has been inspected by Assistant Engineer, Rampurhat on Date 20/03/2022 and found that the condition of building is Safe and satisfactory.

The Safety certificate is issued as per the request by the school authority.

Copy to1. The Director, St. Paul's International School, Rampurhat, Birbhum

 25-03-22
Junior Engineer
Birbhum Division, P.H.E Dto
Suri, Birbhum


Assistant Engineer
PWS Birb-Sub-Div.
P.H.E. Dto.


PRINCIPAL
St.Paul's International School


Manager
St.Paul's International School